

3D Printing 101

3D printing is a maturing technology suitable for producing functional prototypes, manufacturing aids, visual models, and end products. Commonly utilized 3D printing technologies include fused filament fabrication (FFF) and selective laser sintering (SLS).

Fused Filament Fabrication (FFF) Material in filament form is fed through a printer's nozzle onto a build plate to print a part layer by layer based on a 3D model. Selective Laser Sintering (SLS)

Laser is used to sinter material in powder form layer by layer to print a part based on a 3D model.

Fabrication Technique	Pros	Cons
Fused Filament Fabrication (FFF)	 Desktop FFF printers are more affordable Materials are lower cost Scalable solution 	 Post-process operations to remove supports Closed printing systems which limit materials to those offered solely by the 3D printer manufacturer
Selective Laser Sintering (SLS)	 Cost effective when printing multiple parts at a time No support material needed 	 Long print times when multiple parts are not being printed at the same time More expensive and larger printers Post-process operation to recycle powder
Computer Numerical Control (CNC)	 Wide variety of materials and surface finishes can be utilized Efficient for very high precision and repeatable results 	 Expensive initial investment Machine setup and calibration can be time consuming Requires training to operate Subtractive process results in material cut away and wasted
Injection Molding	 Highly automated Fast production times Cost effective for high volume production runs 	 Expensive initial investment Requires training to operate High tooling cost and not cost effective for low volume production runs

Filaments come in two main sizes – 1.75mm & 2.85mm depending on the 3D printer. It is important to understand what brand printer the customer has and the size filament they are using. Powders typically come in 55 lb. bags/boxes in a specific particle size; powders for SLS are more universal.

Due to the lack of recyclability of powder, most customers need between 110-220 lbs. for sampling on SLS 3D printers.

3D printers are available in open and closed systems:

A **closed 3D printing** system can only use the manufacturer's proprietary resin. 3D Systems, Stratasys, and Markforged are more widely used closed systems.

An **open 3D printing system** can utilize filament from various manufacturers. Ultimaker, Raise3D, Prusa, and MakerBot (owned by Stratasys) are open system printer manufacturers. Open systems allow more freedom in proper material selection and multiple sources to purchase from.

Chase Plastics offers materials for open and closed 3D printers. A majority of our material offering is dedicated to open system printers, with SABIC Filament Refill Models for Stratasys Fortus[™] Classic 3D printers.



Redefining Resin Distribution*

6467 Waldon Center Drive • Clarkston, MI 48346 248-620-2120 • orders 800-232-4273 • fax 248-620-3192 ChasePlastics.com

f 🔰 in 🔘 🚟

© October 2020, Chase Plastic Services, Inc.

The marks identified herein are registered trademarks of their respective owners. Any recommendation by Chase Plastics' personnel for the use of any material is based on tests or experience believed to be reliable. However, since the final processing and use of the product are beyond our control, we make no warranty as to such use or effects incidental to such use, handling or sale.